

Subject: Trailer Lights Inoperative, Update Programming

(Flashing) Trailer Control Module

Model(s): Touareg with Trailer Towing

Accessory Package

Group: 01

Number: 05-12

Date: July 27, 2005

Supersedes T.B. Group 01 number 04-11 dated May 17, 2004 due to removal from Required Vehicle Update status.

Condition

2004

Trailer Lights are inoperative.

May require Trailer Control Module (J345) "Update - Programming" to increase electrical capabilities from 4 amps / 50 watts to 8.3 amps / 100 watts to accommodate trailers with large electrical draw.

Service

Tool requirements

- ♦ VAS 5051 or 5052 (with Basis CD V.06.05 and the Brand CD V.06.48 or higher) with old diagnosis logs erased prior to start.
- ◆ "Update Programming" (flashing) CD W42TOUAREGTHCD.
- ◆ VAS 5051: connected to vehicle and to 110V AC Power supply at all times during procedure.
- ◆ VAS 5052: connected to vehicle with battery voltage requirements met.



Additional copies the "Update Programming" (Literature Number CDW42TOUAREGTHCD) may be ordered from the Volkswagen Technical Literature Ordering Center at www.vw.ddsltd.com, or by calling 1-800-544-8021 from 8:00 a.m. to 8:00 p.m. EST Monday through Friday. This number can be dialed in both the United States and Canada.

C 01-05-12 1 of 7

Vehicle requirements

- Battery MUST have minimum no-load charge of 12.5V (failure to maintain voltage during update process can lead to Control Module failure) (you must use an approved battery charger to maintain battery voltage).
- Any appliances with high electromagnetic radiation (i.e. mobile phones) switched OFF.
- ◆ No Stored DTC's, erase any stored DTCs (see Tip on page 3).

① Note:

- Non-observance of the following points may lead to Control Module failure!
- ◆ VAS 5051 or 5052 must always be connected to the approved power supply at the approved voltages. Under no circumstances should the power supply be interrupted or the diagnostic connector unplugged during the flash procedure.
- Any appliances with high electromagnetic radiation (i.e. mobile phones) must be switched OFF.

C 01–05–12 2 of 7



performing PRIOR to procedure "Update - Programming" (flashing) the **Control Module:**


◆ ALL fault memories must be interrogated and erased.




Failure to erase ALL fault memories may cause "Update - Programming" (flashing) procedure to fail!



- When performing the reflash procedure, ALL DTCs for all systems are erased.
- DTCs linked to Guided Fault Finding function tests will be lost. Therefore, always address stored DTCs for Customer concerns unrelated to the reflash procedure first.
- Select vehicle system "69 Trailer function".




- Change coding from "1" to "2".
- Finish coding by selecting the backward arrow **◄** on navigation bar.
- Change coding from "1" to "2".
- Finish coding by selecting the backward arrow < on navigation bar.
- Select Diagnosis function "06 End output".
- Select Diagnosis function "00 Collection services".
- Select "Check DTC memory complete system". which will interrogate all fault memories.
- Erase ALL fault memories.



C 01-05-12 3 of 7



Please give copies to all Technical Bulletin your VW Technicians



Once ALL fault memories have been erased:

- Install "Update Programming" (flashing) CD in diagnostic tool.
- Select vehicle system "69-Trailer function".
- Select "Update Programming" option at bottom of screen.



Once "Update - Programming" function has been started, switching ignition OFF or disconnecting the diagnostic connector may completely destroy the Control Module.


Vehicle Self-Diagnosis	69 - Trailer function	
Update - Programming	Control Module Part Number	
	Ctrl. Mod. description / software level	
	Coding XXXXX	
Programming can be carried out.	Dealership number XXXXX	
WARNING!		
The programme version stored in the control unit will be erased		
It will be programmed with the new version XXXX		
The erasing programming process will last roughly XX minutes		
The part number in the control unit identification may change.		
Vehicle specific data (coding, adaptation etc.) might be lost. It must		
be checked after successful programming		
After the continue button has been pressed the process cannot be cancelled.		
IMPORTANT PLEASE NOTE:		
Switching ignition off or disconnecting the diagnostic connector		
during programming may completely destroy the control module!		
Test Go to	Print Colon	
Instruments		
_	01-A359	
	01 A333	

- "Update Programming" (flashing), performing
- After selecting "Update Programming" function:
 - By selecting the forward arrow ▶ on navigation bar, the programming procedure begins.

C 01-05-12 4 of 7




Please give copies to all Technical Bulletin your VW Technicians



- Similar screen appears:
 - ◆ Previous data in the Control Module is erased and new data is being transferred to the module from the flash CD.




Approx. flashing time is 5 minutes.





- If, during the "Update Programming", a fault message is displayed:
 - Confirm that VAS 5051 or VAS 5052 diagnostic tool power supply is adequate and that ALL appliances with high electromagnetic radiation (i.e. mobile phones) are switched OFF.
 - The "Update Programming" (flashing) process must then be started from the beginning using the "Repeat" button (arrow). DO NOT use the "Cancel" button.






On NO occasion should the "Cancel" button be selected.

Once "Update - Programming" (flashing) is complete:

- Similar screen appears.
 - ◆ New Control Module Part Number and updated software level is displayed at (arrows).

C 01-05-12 5 of 7





Once "Update - Programming" (flashing) is complete, the control module must be re-initialized.

- ◆ The tester requests you to switch the ignition OFF.
 - Switch ignition OFF.



 Wait at least 20 seconds before switching the ignition back ON (failure to wait at least 20 seconds may damage the Control Module).

After waiting 20 seconds:

- Switch ignition ON.

After switching ignition ON, the Control Module has been re-initialized, however, fault memories must now be erased.

- Select the "Continue button"

Vehicle Self-Diagnosis	69 - Trailer function	
Update - Programming	Control Module Part Number	
Erase fault memory	Ctrl. Mod. description / software level Coding XXXXX Dealership number XXXXX	
The programming causes fault records in related control units. The fault memories of all control units in the vehicle must be erased.		
Pressing the Continue button will automatically erase the fault memories.		
Pressing the Back button will not erase fault memories		
Go to	Print ? A D	
	01-A362	

Fault memories, erasing after "Update - Programming" (flashing)


Due to the CAN bus system, fault messages will be stored in various Control Modules during programming.

- To erase ALL fault memories:
 - Confirm by selecting the forward arrow ▶ on navigation bar.
 - ◆ Erase fault memories takes approx. 15 minutes.

C 01–05–12 6 of 7



Please give copies to all Your VW Technicians Technical Bulletin



Once fault memories have been erased:

- Similar screen appears.
 - ◆ Function ended appears at bottom of screen.

Vehicle Self-Diagnosis	69 - Trailer function	
	Control Module Part Number	
Select	Ctrl. Mod. description / software le	
diagnosis function	Coding XXXXX	
· ·	Dealership number XXXXX	
02 - Interrogate fault memory		
03 - Final control diagnosis		
04- Basic settings		
05 - Erase fault memory		
06 - End output		
07 - Code control unit		
08 - Read data block		
09 - Reading individual measuring value		
10- Adaption		
11 - Log-in procedure		
Test Go to Instruments	Print ?	
	01-A364	

- ◆ Similar screen appears.
 - ◆ New Control Module Part No: 7L0 907 383G and updated software level "8854" will appear at arrows.
 - ◆ Flash CD can now be removed from VAS 5051 or VAS 5052 Diagnostic tool.
 - Print the "69-Trailer function" screen to verify Control Module update software level.
 - Attach print to vehicle Repair Order.

When procedure applies to vehicles

within the New Vehicle Limited Warranty, use the following:	
Claim Type:	W2
Part Identifier:	6690
Damage Code:	6690 39 000 1
Labor Operation: Includes all operations necessary to complete repair	6690 9999 Use A-Time Maximum A-Time allowed 60 TU
Diagnostic Time:	No Diagnostic time allowed
Claim Comment: Type "As per Technical Bulletin V0105XX" in comment section of	

C 01–05–12 7 of 7

Warranty Claim