



Important!

Please give copies to all
your VW Technicians

Technical Bulletin

Vehicle Delivery Information

Subject: **Headlights, Adjustment at Perfect Delivery Inspection
(PDI) Not Required**

Group: **00**

Number: **03-05**

Model(s): **All**

2003, 2004

Date: **June 24, 2003**

Condition

Current instructions require Headlight adjustment during PDI.

Production

Beginning M.Y. 2003, headlights on all models are adjusted with automatic assembly equipment at the correct VOL specification of 0.7

These settings correspond with the specifications for the Hella Universal Beamsetter Series IV aiming equipment used by all Dealers.

Service

Headlight adjustments are no longer necessary at the PDI and should only be performed if a customer concern is evident.

If a customer voices concerns regarding headlight aiming of their vehicle:

- Check (and adjust if necessary) to 0.7 VOL using the VAS 5107 (Hella Universal Beamsetter Series IV aiming equipment) according to instructions in Repair Manual - Repair Group - *Maintenance*.