

Technical Bulletin



Condition

Ignition/Starter Switch -E415- Deletion of Emergency Key Release Feature

48 06 03 Sept. 11, 2006 2010626, Supersedes T.B. Group 48 number 04-01, dated September 30, 2004 due to inclusion into ElsaWeb.

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Touareg	2004	All	All	7L_4D000001	7L_4D080433
Phaeton	2004	All	All	3D_48000001	3D_48012170

Technical Background

The ignition/starter switch -E415- has been changed to conform to Federal Motor Vehicle Safety Standard 114.

Prior to this change, the key could be removed from the ignition/starter switch by pressing the release button under a small protective cap on the ignition/starter switch when the shift lever was in a different position from Park.

The new ignition / starter switch, Part No. 3D0 905 865F 01C does not have the release feature.

Production Solution

Installation of new ignition/starter switch -E415-. as of:

Touareg	WVGHH77L44D080434
Phaeton	WVWAF63D348012171

Technical Bulletin



Service

When ignition/starter switch -E415- replacement is necessary the latest version of Part No. 3D0 905 865F 01C must be installed.

Warranty

Information only.

Required Parts and Tools

No special tools required.

No special parts required, always see ETKA for the latest parts information.