



# Important!

Please give copies to all  
your VW Technicians

# Technical Bulletin

Subject: **Headlights, Moisture Accumulation**

Group: **94**

Number: **03-01**

Model(s): **Touareg**

**2004**

Date: **Aug. 1, 2003**

## Condition

Moisture accumulating in headlamp.

## Service

◀ Headlight assemblies are vented and will collect moisture on the headlight lens under some climatic and geographical conditions.

Moisture will evaporate after headlights have been ON for approx. 10 minutes.

- NO action is necessary. DO NOT replace headlights for this condition.

