

Technical Bulletin



Condition

MIL ON - Misfire DTC Stored After Cold Start

Sporadically, after cold start, the engine may run slightly rough for a few seconds and the MIL may illuminate with a DTC for misfire on one or more cylinders. DTC P0300, P0301, P0302, P0303, P0304 stored in ECM data memory.

01 06 24 Dec. 5, 2006 2013103

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2005 - 2007	2.0L (BPY)	All	All	All

Technical Background

The rough running condition disappears a few seconds after cold start and does not exist with a warm engine.

Production Solution

No production change required.

Service

- Follow normal Guided Fault Finding Diagnosis.
- If diagnosis results are inconclusive, **DO NOT** carry out any repair or replace any part.
- If condition persists, contact the Volkswagen Technicians Helpline for further assistance.

Warranty

Information only.

Required Parts and Tools

No Special Tools required.

No Special Parts required. Always see ETKA for the latest part(s) information.