

# Technical Bulletin



## Condition

### Customer States, CD Not Ejecting or Radio Face Plate Buttons Peeling

91 06 08 Oct. 20, 2006 2013084

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Touareg	2003 - 2007	All	All	All	All

## Technical Background

CD Not Ejecting or Radio Face Plate Buttons Peeling.

## Production Solution

New Radios installed.

## Service

### Tool requirements

VAS 5051 or VAS 5052 (with Base CD V.10.01 and the Brand CD V.10.70.00 or higher).

### Vehicle requirements

Battery **MUST** have a minimum no-load charge of 12.5V (failure to maintain voltage during update process can lead to ECM failure) (it is advised to use an approved battery charger to maintain battery voltage).

VAS 5051: connected to vehicle and to 110V AC Power supply at all times during procedure.

VAS 5052: connected to vehicle with battery requirements met.

- Connect the VAS 5051 or VAS 5052 to the vehicle.
- Verify the radio part number using vehicle self-diagnosis.
- Select Radio and part number will be at the right top of the screen.

If radio part number is anything other than 7L6035180H\*:

- Install radio with Part No. 7L6035180H

See Repair Manual Group 91 in ElsaWeb for removal and installation instruction.

# Technical Bulletin



## Warranty

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:	
Claim Type:	W2
Part Identifier:	9130
Damage Code:	9130 40__ * 2
Labor Operation:	91301900 = 20 TU
Diagnostic Time:	No Additional Diagnostic Time Allowed
Claim Comment: Input "As per Technical Bulletin 2013084" in comment section of Warranty Claim.	

\* Code per warranty vendor code policy.

## Required Parts and Tools

Description	Part No:	Quantity
Radio	7L6035180H	1

No Special Tools required.