


## Abnormal Noise When Clutch Pedal is Depressed

Service  
Category Drivetrain

Section Manual Transmission/Transaxle

Market USA

Scion Supports  
ASE Certification 

thanks  
Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2013 - 2016	FR-S	Transmission(s): 6MT

### Introduction

Some 2013 – 2016 model year FR-S vehicles equipped with a manual transmission may exhibit an abnormal noise, such as a squeak, grind or groan type noise when the clutch pedal is depressed. Follow the procedure below to address this condition.

### Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
TC9021	R & R Bearing Release	3.7	SU003-00802	91	19

#### APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

### Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
SU003-00802	SU003-07349	Bearing Assy, Clutch Release	1