


R32: Early model radiator hose issue

Old Hose (See rub mark on top hose)



New Hose (Notice protective sleeve and rubber reinforcement) VW P/N 1J0 121 096 CJ

