



**Important!**

Please give copies to all  
your VW Technicians

# Technical Bulletin

## Vehicle Delivery Information

**Subject: Fault Code 00778 000 Stored at the Perfect Delivery  
Inspection (PDI)**

**Group: 00**

**Number: 06-03**

**Model(s): Touareg**

**2004 ► 2006**

**Date: Mar. 1, 2006**

### Condition

At the PDI, the fault code 00778 000 is stored in Steering Wheel Electronics.

May be caused when the Battery Cut-off switch is disconnected for removal.

### Service

- ◆ Do Not replace any components for this fault code.
- The fault appears after disconnecting the Battery Cut-Off Switch, see subject matter "Battery Cut-Off Switch, Disconnecting and Removing During the Perfect Delivery Inspection (PDI)", as stated in Technical Bulletin 00-05-01 or later.
- After disconnecting the Battery Cut-Off Switch, the steering angle sensor will temporarily lose calibration (light will illuminate) and must relearn its position.
- The air suspension will temporarily lose communication with the steering angle sensor (light will illuminate).
- Drive vehicle forward with wheels in the straight-ahead position for approximately 45ft (13.7M) to reset the fault code.