



Important!

Please give copies to all your VW Technicians

Technical Bulletin

Subject: Ignition/Starter Switch -E415- Deletion of Emergency Key Release Feature

Group: 48

Number: 04-01

Model(s): Touareg & Phaeton

2004 ► See Table

Date: Sept. 30, 2004

Condition

The ignition/starter switch -E415- has been changed to conform to Federal Motor Vehicle Safety Standard 114.

Prior to this change, the key could be removed from the ignition/starter switch by pressing the release button under a small protective cap on the ignition/starter switch when the shift lever was in a different position from Park.

The new ignition/starter switch (Part No. 3D0 905 865F 01C) does not have this release feature.

Production

New ignition/starter switch installed in vehicles starting with the following VINs:

Touareg	WVGHH77L44D080434
Phaeton	WVWAF63D348012171

Service

When ignition/starter switch -E415- replacement is necessary:

- ◆ Latest version (Currently Part No. 3D0 905 865F 01C) must be installed.

CAUTION!

Part numbers listed in this bulletin are for reference only. Always check with your Parts Dept. for the latest parts information.