



Important!

Please give copies to all
your VW Technicians

Technical Bulletin

Subject: **Rear Seat Armrest Lid, Disengaged from Armrest**

Group: **68**

Number: **03-01**

Model(s): **Touareg**

2004

Date: **Aug. 1, 2003**

Condition

Rear seat armrest lid is disengaged from the armrest.

When an object interferes with closing the lid, it may cause the lid to break away from the armrest.

Service

Do not replace armrest for this condition.

This is a break-away feature of the armrest lid and is designed to help eliminate damage to the armrest lid or object in the event that the lid is closed on the object.

- Remove cup holder insert.
- Reposition armrest lid onto hinges and snap into place.
- Ensure armrest lid opens and close properly.
- Reinstall cup holder insert.