



Important!

Please give copies to all
your VW Technicians

Technical Bulletin

Subject: **Radio, Insufficient Bass Output**

Group: **91**

Number: **05-05**

Model(s): **Touareg with Radio Navigation System (Sound II)** 2004 ▶ 7L94D015720 Date: **Oct. 21, 2005**

Supersedes T.B. Group 91 number 04-06 dated May 17, 2004 due to Removal from Required Vehicle Updates Category.

Condition

Radio system exhibits insufficient Bass (low frequency) output.

Production

New radio amplifier as of VIN: 7L94D015720.

Service

 **Tip:**


Do Not complete this technical bulletin if OTIS shows the BE code is complete.

Part numbers listed in this bulletin are for reference only. Always check with your Parts Dept. for the latest parts information.

Procedure:

◀ For vehicles with insufficient radio bass output, which are equipped with radio/navigation system (Sound II), built prior to VIN: 7L94D015720:

- Replace with new radio amplifier, Part No. 7L6 035 466. See Repair Manual, *Repair Group 91, Amplifier, Removing and Installing.*





Important!

Please give copies to all
your VW Technicians

Technical Bulletin

**When procedure applies to vehicles with-
in the New Vehicle Limited Warranty, use
the following:**

Claim Type:	W2
Part Identifier:	9131
Damage Code:	9131 40 xxx 2
Labor Operation:	91311900 90TU
Diagnostic Time:	No Diagnostic Time Allowed

**Claim Comment: Type "As per Technical
Bulletin V910505" in comment section of
Warranty Claim**