

Technical Bulletin



Condition

Washer Jets (Front or Rear), Restricted

92 06 07 Dec. 11, 2006 2010427 Supersedes T. B. Group 92 number 05-01 dated Mar. 14, 2005 due to inclusion into ElsaWeb.

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2003 - 2006	All	All	All	All

Technical Background

Window washer spray jet will not spray or has reduced flow because of restriction.

Production Solution

No production change required.

Service

Remove restricted nozzle. Refer to Repair Manual Group 92 Windshield wiper and washer system – Windshield washer jets, removing and installing in ElsaWeb.



Tip:

When using compressed air to clear the washer jet, blow in direction of flow only.

- Clear obstruction using compressed air.



Tip:

If obstruction can not be cleared, replace the washer jet.

- Before installing new or original washer jet, flush the washer lines by running the washer pump without the washer jet for 30 seconds.
- Install the new or original washer jet and verify operation. Refer to Repair Manual Electrical equipment Group 92 - Windshield wiper and washer system “Windshield washer jets, checking and adjusting” in ElsaWeb.

Technical Bulletin



Warranty

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:	
Claim Type:	W2
Part Identifier: Front	9266
Damage Code: Front	9266 16 _ _ _ * _ **
Labor Operation: Front	92661900 = 20 TU
Part Identifier: Heated Front	9263
Damage Code: Heated Front	9263 16 _ _ _ * _ **
Labor Operation: Heated Front	92631900 = 20 TU
Part Identifier: Rear	9294
Damage Code: Rear	9294 16 _ _ _ * _ **
Labor Operation: Rear	92941950 = 30 TU
Labor Operation: Additional for Lift Gate Panel	70921900 = See ElsaWeb for applicable TU
Diagnostic Time:	No Additional Diagnostic Time Allowed
Claim Comment: Input "As per Technical Bulletin 2010427" in comment section of Warranty Claim.	

* Code per warranty vendor code policy.

** Use 1 for repair or 2 for replace..

Required Parts and Tools

No Special Parts required. Always see ETKA for the latest part(s) information.

No Special Tools required.