



Important!

Please give copies to all
your VW Technicians

Technical Bulletin

Vehicle Delivery Information

**Subject: Battery, Checking Terminal Clamps for Correct Seating
at Perfect Delivery Inspection (PDI) Not Required**

Group: 00

Number: 03-04

Model(s): All

2004

Date: June 20, 2003

Condition

Current PDI instructions require checking the battery terminal clamps for correct seating.

Service

Beginning with 2004 M.Y., it is no longer necessary to check battery terminal clamps for correct seating.