



# Important!

Please give copies to all  
your VW Technicians

# Technical Bulletin

Subject: **Front Disc Brakes, Replacing Brake Pads For  
Intermittent Squeal**

Group: **46**

Number: **05-01**

Model(s): **Touareg 3.2L V6 (Eng. codes BMX, BAA)  
4.2L V8 (Eng. codes AXQ, BHX)**

**2005 see  
VIN Below**

Date: **Jun. 17, 2005**

**Supersedes T.B. V460403 dated Nov. 12, 2004 due to brake system clarification.**

## Condition

Brake pad composition may in time result in intermittent squeal from front brakes.



### Tip:

*Condition does not affect brake performance.*

## Production

Brake Pad composition changed as of VIN:  
7L\_5D038749.

(PPC) Port Processing Centers installed  
Brake Pad Kit brake pad kit Part No:  
7L0 698 151F (vehicles are identified by a  
red dot on inside rearview mirror).

## Service

This procedure should be applied as follows:

- Only on 2005 MY vehicles before VIN: 7L\_5D038749.
- Only on vehicle with the above listed engine configurations.
- Only on vehicles without red dot on inside rearview mirror.
- Only on vehicles with 17 inch brake system.
- Depending on vehicle disposition (sold & delivered or In Dealer Inventory) see page 2 for instructions.



# Important!

Please give copies to all your VW Technicians

# Technical Bulletin

### Dealer inventory:

- The following must be performed (during the PDI) on all applicable vehicles as listed on page 1.

Inspect each vehicle for a red dot on the inside rearview mirror.

If mirror has red dot:

- **Do Not** perform this Technical Bulletin.

If mirror does not have red dot:

- Replace front brake pads using brake pad kit Part No: 7L0 698 151F (see Repair Manual *Brake System* Group 46 – Brakes Mechanical components, Front brakes, Brembo 17” and 18” calipers, servicing).



### Tip:

*DO NOT* replace front brake rotors as they will not be affected by this exchange.

<b>When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:</b>	
<b>Claim Type</b>	<b>W2</b>
<b>Part Identifier:</b>	<b>T636</b>
<b>* Damage Code:</b>	<b>T636 20 xxx 2</b>
<b>Labor Operation:</b> Includes all operations necessary for repair	<b>T6369998 70TU</b>
<b>Claim comment: Type “Per Technical Bulletin V460403” in comment section of Warranty claim.</b>	

\*) xxx = vendor code for parts