**Technical Bulletin** 

Please give copies to all your VW Technicians

Important!


# Vehicle Delivery Information

#### Subject: Engine, Upper Covers Missing at PDI

Model(s): Touareg

#### 2004

Group: 00 Number: 03–09 Date: Nov. 13, 2003



## Condition

Upper engine covers not installed when vehicle arrives at Dealership

### Production


Upper engine covers -A- and hood rod covers -B- are no longer supplied beginning with VIN:

- V6: WVGBC67L44D028106
- V8: WVGCM67L44D028205

#### Service

For vehicles beginning with the VINs listed above:

- Vehicles may arrive at Dealership without upper engine covers -A- and hood rod covers -B-.
- NO action is required. DO NOT order and install engine covers.
- Covers are not considered missing equipment.



## C 00-03-09

1 of 1

© 2003 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property right of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.