

US-129 Rockslide

Aerials and Ground Level

March 19, 2010



Rocks precariously sit near the road's edge.



Rocks overhang near the road just out of view below.



Large rock near road edge.



Aerials of rockslide on US-129.



Aerials of rockslide on US-129.