



Important!

Please give copies to all
your VW Technicians

Technical Bulletin

Subject: Automatic Transmission, Repairing

Group: 37

Number: 05-01

Model(s): All with 5 and 6 Speed Automatic Transmission

Date: Sept, 20 2005

Supersedes T.B. Group 37 Number 02-04 dated Dec. 12, 2002 due to addition of 6 speed transmission.

Condition

5 or 6 speed automatic transmission requires repair or replacement.

Service

Whenever repairing or replacing a 5 or 6 speed automatic transmission:

- Make a copy of the attached "5 and 6-Speed Automatic Transmission Concern Report".
- Prior to performing any repairs, fill the report out as completely as possible following the instruction below.
- Attach a copy of this report to the repair order and keep in the permanent vehicle file.
- Enclose a copy of this report along with any transmission parts requested by the Warranty Test Center, and/or when returning for CORE credit.

Form Instruction

Page 1 generic information (Dealer name, Dealer number, model information etc.):

- Fill out all fields indicated with an asterisk.

Page 1 and 2 Concern specific information (Fluids, DTCs Operating conditions etc.):

- Fill out areas associated with concern (i.e. if leaks are checked on page 1, fill out Leakage Detail on page 2).



5 and 6-Speed Automatic Transmission Concern Report

Complete only the fields associated with this concern.

Noise

Type of noise (whine, rattle, bang, etc.):

Does noise increase decrease
with increasing decreasing
 engine speed vehicle speed?

Does the noise occur in Neutral? Yes No

Customer states noise getting worse? Yes No

Fluid Condition Detail

ATF

Color: _____

Odor: _____

Contamination Type: _____

Differential Fluid (circle) **Front** **Center** **Rear**

Color: _____

Contamination Type: _____

Shift Quality Detail

Circle or check appropriate number or area and describe where necessary.

Does concern occur:

When moving selector lever from

N-D N-R R-P P-R D-S

On sudden load change

acceleration deceleration

Erratic (please explain) _____

Leakage Detail

Use picture / drawing / sketch if possible to show location (attach drawing).

Vent transmission front axle drive

center differential rear differential

Output flange left right rear

Drain plug transmission front axle drive

center differential rear differential

Weep hole (if applicable)

front center rear

Oil cooler pipe (if applicable)

transmission radiator other

(explain)

Oil cooler, banjo bolt seals

Oil pan

Converter housing

Various cover plates: _____

Joining housings: _____

Others / Remarks: _____

Additional Information: _____

Important safety information: When driving or riding in airbag-equipped vehicles, never hold test equipment in your hands or lap when the vehicle is in motion. Objects between you and the airbag can increase the risk of injury in an accident. During a road test in an airbag-equipped vehicle, test equipment must always be fastened to and operated from the rear seat by a second technician.

©2005 Volkswagen of America, Inc. All rights reserved. Information contained in this worksheet is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher. All requests for permission to copy and redistribute information should be referred to Volkswagen of America, Inc.